

FIELD INSPECTION REPORT

(Rajendra - Jagdishpur)

Date of Inspection: 03/12/2020 | District: Bhagalpur.

Division: Bhagalpur | Length (Km): 1.95 km.

Name of the Road: P.W.D. Road to Makaspur.

Scheme/Programme: MAINTENANCE

Package No.: Group No. 04 | Road Id No.: 20703201027

Status of the Project: Ongoing/completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Y
4	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	—

NAME:

Radhe Ramesh Singh

DESIGNATION:

(Assistant Engineer)

(Signature)

31/12/20
J.E.
03/12/20
R.E.