

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 1.42 km	
Name of the Road: Pista to Karampur			
Scheme/Programme: MAINTENANCE			
Package No.: Group No. 03		Road Id No.: 207032-01032	
Status of the Project: Ongoing / completed / Under Maintenance			
Work is a case of: New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Cmpaction of flank/slope & raincuts if any	Yes/No	NA
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	YES
4	Compliance History		
a)	Status of ATR's & any others		ND

Overall Rating: WORK in Progress

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	—

NAME:

Radhe Raman Singh

DESIGNATION:

(Assistant Engineer)

(Signature)

3/12/20
AR