

# FIELD INSPECTION REPORT

(Block - Shahkud)

Date of Inspection : 03/12/2020		District : Bhagalpur	
Division : Bhagalpur		Length (Km) : 2.75 km	
Name of the Road : Shiv Shankarpur PWD Road to Damodarapur.			
Scheme / Programme : MAINTENANCE			
Package No. / Group No. - 8		Road Id No. : 20703201036	
Status of the Project : <input checked="" type="checkbox"/> Ongoing / <input type="checkbox"/> Completed / <input type="checkbox"/> Under Maintenance			
Work is a case of : <input checked="" type="checkbox"/> New Connectivity / <input type="checkbox"/> Up gradation / <input type="checkbox"/> Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	} NA
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	} NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Cmpaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	} NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards / <input checked="" type="checkbox"/> informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating : Work has not been started yet.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	NA

*N*  
03/12/2020  
(Signature)

NAME : Neeraj Kumar

DESIGNATION : J-E