

FIELD INSPECTION REPORT

(Block - Jagdishpur)

Date of Inspection: 03/12/2020		District: Bhagalpur
Division: Bhagalpur		Length (Km): 1.00 Km.
Name of the Road: Timpuliga to Rikheaditi Road.		
Scheme/Programme: MAINTENANCE		
Package No.: Group No. 04		Road Id No.: 207032.01038
Status of the Project: Ongoing / completed / Under Maintenance		
Work is a case of: New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/O
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating: Work has not been started yet.

Satisfactory(S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	—

NAME: Radho Raman Singh
DESIGNATION: Assistant Engineer

3/12/20
J.E.

03/12/20
(Signature) A.E.