FIELD INSPECTION REPORT

(Block - Jagderton)

Torto of I	nspection: 03/12/2020 District:			
Division:	Bhagalpur. Length (Km): 2.30 Kim.			
	Dail Milli Dad Mark			
Name of	the Road: Baluachack - Bharokhar Road.			
	Programme: MAINTENANCE			
Package	No.: Group No. 04 / Road Id No.			
	Ongoing /completed/Under Maintenance			
	a case of : New Connectivity/Up gradation/ Maintenance			
SL. No.	Parameters to be checked	Remarks		
1	Pavement			
a)	Road Junction condition	_S/U)	
b)	Condition of Surfacing	.s/⊎	MA	
c)	Riding Quality	s/U	17 "	
d)	Road Camber	S/Ú	<u> </u>	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	AH }	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	41	
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No	1	
2	Cross Drainage	100000		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/I	H (H	í
	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/	-	
<u>b)</u>	Condition of railings/slab/approach for Bridges	S/SRI/	U	
c)	Road Furniture	g 4, 46		
a)	Whether sign boards/informatory/cautionary Board/km & 200 stones/Pavement road markings are provided and maintained	0m Yes/N	40 MD	
	Compliance History		200	
al	Status of ATR's & any others			
The second second	Rating: Work in brogrey.			
	Satisfactory(S)	SR	I	
	Satisfactory but requires Improvement (SRI)	-		
	Unsatisfactory(U)	iming kr	ro	

NAME: Radha Raman Singh Millent Expiner