

# FIELD INSPECTION REPORT

Bhuc - Sultengaj.

Date of Inspection: 3.12.20 | District: - Bhugabur.  
 Division: (Sultengaj) Bhugabur Length (Km): 1.240 km.  
 Name of the Road: Asengaj Karharia R.E.O to Uchagaom.  
 Scheme/Programme: | MAINTENANCE  
 Package No.: Grants No - 10 | Road Id No.: 20703202034.  
 Status of the Project: | Ongoing/completed/Under Maintenance  
 Work is a case of: | New Connectivity/Up gradation/ Maintenance

SL. No.	Parameters to be checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

NA

NA

Overall Rating: work has not been started yet.

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)