

FIELD INSPECTION REPORT

Bhokra - Sultangunj.

Date of Inspection:	3.12.20	District:	Bhagalpur.
Division:	(Sultangunj) Bhagalpur	Length (Km):	6.30 km.
Name of the Road:	Gram Nayaam to maindih Herma.		
Scheme/Programme:	MAINTENANCE		
Package No.:	Group No - 10	Road Id No.:	20703202054
Status of the Project:	Ongoing / completed / Under Maintenance		
Work is a case of :	New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Note - Work has NOT been started yet.

(Signature)

NAME: H.N. Mahato.

DESIGNATION: E.E. Bhagalpur.