

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 District: Bhagalpur		
Division: Bhagalpur Length (Km): 0.930 km.		
Name of the Road: REO Road to Mathurapur		
Scheme/Programme: MAINTENANCE		
Package No.: Group - 0% Road Id No.: 20703202106		
Status of the Project: Ongoing/completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	NA S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : NA

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Note. Work has not been started

NAME:

DESIGNATION:

Ashman
03/12/2020
J.E.
Mathurapur

(Signature)

3/12/2020
अनिमल कुमार
अधीक्षक
01/11/2012