

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020	District: Bhagalpur	
Division: Bhagalpur	Length (Km): 2.00 K.M.	
Name of the Road: Nathnager to Hula Aethan via Kanchha P.C.C. work		
Scheme/Programme: MAINTENANCE		
Package No.: Group - 05	Road Id No.: 2070320A015	
Status of the Project: Ongoing / completed / Under Maintenance		
Work is a case of : New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A.
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

NA

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Note: Pot work is in progress.

NAME:

DESIGNATION:

Ashwan
03/12/2020
J.E.
Nathnager

(Signature)

Signature

31/12/2020
Ghullu