FIELD INSPECTION REPORT

Date o	Date of Inspection: 03/12/2020 District: Phagalows				
Date of Inspection: 03/12/2020 District: Bhazalpur Division: Bhazalpur Length (Km): 2.20 km.					
Name of the Road: Chholi Haridaspur (Marijan Tolas to					
Scheme/Programme: MAINTENANCE					
	Package No.: Urroup - 86 Road Id No.: 20703208115				
Status of the Project: Orgoing /completed/Under Maintenance					
	a case of : New Connectivity/Up gradation/ Maintenance	2			
SL. No.	Parameters to be checked		Remarks		
1	Pavement	1			
a)	Road Junction condition		s/U		
b)	Condition of Surfacing		s/U		
c)	Riding Quality	1	s/U		
d)	Road Camber	M	s/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Cpmpaction of flank/slope & raincuts if any)	Yes/No		
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U		
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	NA	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	,,,,,	S/SRI/U		
3	Road Furniture				
a) [Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No		
4 (Compliance History		The State		
a) 9	tatus of ATR's & any others	THE PARTY OF THE P			

Overall Rating:	N	A
-----------------	---	---

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Nite.

Work has not been started.

NAME:

DESIGNATION:

Matrader 1.C. (Signature)

20 JUN 2015 3