

WORK Yet to be Started

Block - SABOUR

FIELD INSPECTION REPORT

Date of Inspection : 3.12.2020		District: Bargarh	
Division : Kalagpur		Length (km): 0.883 km	
Name of the Road: Blith Khandi PNH (PNH Road) To Bari Tahasilpur.			
Scheme/Programme: MAINTENANCE		(New Maintenance Policy)	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	NA
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	Yes/No	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	S/SRI/U	NA
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture	Yes/No	NO
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	N/A	
a)	Status of ATR's & any others		

Overall Rating : WORK Yet to be Started.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	N/A
Unsatisfactory (U)	

A.A
3.12.2020
AE

(Signature)
3/12/2020

NAME: