

FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 1.860 km.	
Name of the Road: RFO Road to Panchakathia			
Scheme/Programme: MAINTENANCE			
Package No.: Group - 06		Road Id No.: 20703301021	
Status of the Project: Ongoing /completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
SL. No.	Parameters to be checked		Remarks
1	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber	NA	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Cmpaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating : NA

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

Note. Work has not been started.

NAME:

DESIGNATION:

Atman
02/12/2020
J.E.
Nethnagar

(Signature)

3/12/2020
A. K. Singh