to (chalos pod

FIELD INSPECTION REPORT

Date of	Inspection: 0	3 12 2020 Dis	triet: Bhagalpar	
Division: Kahalgaon				
Name of	f the Road: Pr	1454 Topra Ross	to prigsy Road I	Cali prodo
Scheme	Programme:	MAINTENANCE No	is providenance polic	4
Package			id Id No.:	ex 810)
	f the Project:	Ongoing/Completed/Unde	er Maintenance In tere	
Work is	a case of:	New Connectivity/Up gra	The second secon	Henence
Sl. No.		Parameters to be ch	ecked	Remarks
1.	Pavement	1		
a)	Road Junction condition			SAU
b)	Condition of Surfacing			SA
c)	Riding Quality			SAU
	Road Camber			SAÚ
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
_	Contraction Joints provided or not (CC Pavement)			Yes/No
t)	Compaction of flank/slope & raincuts if any			Yesti
g)				
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			\$/\$RI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
A STATE OF THE PARTY OF THE PAR	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
公司的 的基本的企业	Status of ATR's & any others			No
3)		This Road is	in tender pros	ses.
verall R	Rating :	Satisfactory (S)		. /

I'ms koo.	,
Satisfactory (S)	- >/
Satisfactory but requires Improvement (SRI)	74
Unsatisfactory (U)	1

(Signature)

NAME: