


FIELD INSPECTION REPORT

Date of Inspection : 2.12.20	District: Banka
Division : RWD(W) Division Banka-2	Length (km): 2.58
Name of the Road: Karghauza Modi More to Fulbariya Kala	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BA/BAN/19/0014	Road Id No.: 20703501013
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating

☒ Satisfactory (S)	S
☐ Satisfactory but requires Improvement (SRI)	
☐ Unsatisfactory (U)	


2.12.20
(Signature)

NAME: Bikrama Prasad
DESIGNATION: Assistant Engineer.
Katoriya (Banka-2)