

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Nalanda
Division :	Rajgir	Length (km):	3.550 km
Name of the Road:	Lakshman Bigha to Aranwa Path		
Scheme/Programme:	MAINTENANCE	(3054 MR)	
Package No.:	RM/NA/RAJ/20/0002	Road Id No.:	NEA220001016
Status of the Project:	Ongoing Completed Under Maintenance Note started		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S U
b)	Condition of Surfacing	S U
c)	Riding Quality	S U
d)	Road Camber	S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes No
g)	Compaction of flank slope & raincuts if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings/slab approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

3/12/20
(Signature)

Ranpreet Singh Kumar