

FIELD INSPECTION REPORT

Date of Inspection :	3-12-2020	District:	NAUGDA
Division :	NAUGDA	Length (km):	12.598 Km
Name of the Road:	SONSA - GONAR BIGHA		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	NEA 220001140
Status of the Project:	Ongoing/Complete/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S
b)	Condition of Surfacing	✓S
c)	Riding Quality	✓S
d)	Road Camber	✓S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI
c)	Condition of railings/slab/approach for Bridges	S SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

S

-

-

NAME: J.B. RWD
 (R.K. Saha)

(Signature) [12/20]
 A.B.
 (ARUN SINGH)