

# FIELD INSPECTION REPORT

Date of Inspection : 3.12.2020	District: NAHADA
Division : NAHADA	Length (km): 4.70 km
Name of the Road: SIMIN TO SAID PUR PAKARIA	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: NEA220001152
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ ST
b)	Condition of Surfacing	✓ ST
c)	Riding Quality	✓ ST
d)	Road Camber	✓ ST
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI
c)	Condition of railings/slab/approach for Bridges	S SRI
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NAME:

3/12/20  
R. K. Srivastava  
J.R.  
RWD

(Signature)

3/12/20  
A.B.  
(ARUN SINGH)