

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Nawada
Division :	Nawada	Length (km):	1.00 KM
Name of the Road:	Kadirgani Nawakole wohari road to Jostawan		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 Nawada/03	Road Id No.:	NEA22000/191
Status of the Project:	Ongoing/Completed/Under Maintenance ongoing		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
f)	Contraction Joints provided or not (CC Pavement)	N.A
g)	Compaction of flank/slope & raincuts if any	✓ Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	SRI
c)	Condition of railings/slab/approach for Bridges	SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes No ✓
4.	Compliance History	
a)	Status of ATR's & any others	Informatory and Logo Board not found in the road at the inspection time.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓ SRI
Unsatisfactory (U)	

Arinash
3/12/2020
J-Estimate
(Signature)

NAME: