FIELD INSPECTION REPORT

| ı | P | 7 | ١ |
|---|---|---|---|
| l | 9 | á | 1 |
| | l | | |

| Date of I | nspection: 2 | -12-2020 | District: Aurengabad, | | |
|---|--|--|-----------------------|---------|--|
| Date of Inspection: 2-12-2020 Division: Daydmagar Name of the Road: Fatch pur Deck Scheme/Programme: MAINTENANCE Package No.: | | agar | Length (km): 1.350 | | |
| Name of | the Road: Fe | atchpur Dech | ura road to Dusari. | | |
| Scheme/ | Programme: | MAINTENANCE | | | |
| | | | | | |
| Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance | | | | | |
| SI. No. | a case or. | The second secon | to be checked | Remarks | |
| | | | | | |
| 1. | Pavement | | | S/U | |
| a) | Road Junction condition | | | | |
| b) | Condition of | S/U | | | |
| c) | Riding Quality | | | | |
| d) | Road Camber | | | | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | | |
| f) | Contraction Joints provided or not (CC Pavement) | | | | |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No | |
| 2. | Cross Drainage | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U | |
| 3. | Road Furniture | | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Wes/No | |

Overall Rating

4.

a)

| Satisfactory (S) | S |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Note - Work in Progress.

Compliance History

Status of ATR's & any others

Shormar 2.12.2020 (Signature)

NAME: Namdam Sharma

DESIGNATION: 5E