

FIELD INSPECTION REPORT

Date of Inspection: 03-12-2020		District: Kishanganj	
Division: Kishanganj-I		Length(km): 26.80	
Name of the Road: PWD Jhala Lodhabari Sohiya baigra Nisardara			
Scheme/Programme:		MAINTENANCE	
Package No.: PW RM/KI/KIS/19/0003		Road Id No.: NEA 22 0001296	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance ✓	

Sl. No	Parameters to be checked	Remarks
1.	Pavement	✓S/U
a)	Road Junction Condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No only informatory sign board
4.	Compliance History	
a)	Status of ATR's & any others	ATR Not pending

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory(U)	—

Srijeen Kumar paswan
J.E RWD Jeshagachh
NAME:

03/12/20
(Signature)