FIELD INSPECTION REPORT

| Date of I | | | CTION REPORT | |
|------------------------|---|--|--|---------------------|
| Division | | 3/12/2020 | District: PATNA | · · · · · |
| | | OR | | |
| Name of | the Road: | nihatar to m | Length (km): 2.05 Km | |
| ochemic/ | 1 logramme: | MAINTENANCE | 10199 | |
| Package | No.: m2/H/19 | -20 Danepur / 10 | Road Id No.: | |
| | f the Project: | Ongoing/Completed | 1/Under Maintenance | |
| Work is | a case of: | New Connectivity/U | Jp gradation/ Maintenance | |
| SI. No. | | Parameters to | | Remarks |
| 1 | Pavement | | | |
| a) | Road Junction | condition | | S/U |
| b) | Condition of St | ırfacing | | S/U |
| c) | Riding Quality | | | S/U |
| d) | Road Camber | | | S/U |
| e) | Whether free aggregates in ca | from defects such ase of CC Pavement. | as visible cracks, exposed | Yes/No |
| f) | | nts provided or not (C | CC Pavement) | Yes/No |
| g) | | flank/slope & raincut | | Yes/No |
| ъ) 2. | Cross Drainag | rance en en emperation | | nt _{ur} eq |
| Personal Land Constant | Condition of he | ad walls in Hume pip | e culverts including its painting | S/SRI/U |
| a) | Condition of Al | outment & Wing wall | s, Slab in RCC culverts | S/SRI/U |
| b) | Condition of At | lings/slab/approach fo | or Bridges | S/SRI/U |
| c) | TO STATE AND MAKES TO SEA OF THE | | | |
| a) | Road Furnitur Whether sign stones/Pavemen | 1-/informatory/cs | autionary Board/km & 200m rovided and maintained | Yes/No |
| 4. | Gompliance Hi | - AND THE PROPERTY OF THE PARTY | | |
| a) | Status of ATR's | | | 村 |

Overall Rating

| Satisfactory (S) | |
|---|--|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Kloric not started

200 The Singhoro

(Signature)

NAME: Sylighelis

DESIGNATION: