


FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020	District: MADHUBANI
Division : JHANTHARPUR	Length (km): 1.5 km
Name of the Road: NH-57 to Kharak	
Scheme/Programme: MAINTENANCE	3054 (MR) New Mainlanes
Package No.: MR-N/19-20/Jhantarpur.	Road Id No.: NEA 22000/48
Status of the Project: Ongoing/Completed/Under Maintenance	(work in progress)
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sr. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 3/12/20
 (Signature)

NAME: MD GYASUDDIN
 DESIGNATION: (Asst. ENGINEER)