

FIELD INSPECTION REPORT


Date of Inspection :	03.12.2020	District:	Siwan
Division :	Siwan - 01	Length (km):	2.350 km
Name of the Road:	Siwan - Hasua PWD path Se Hasanpurwa		
Scheme/Programme:	MAINTENANCE	MR-3054	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U S
b)	Condition of Surfacing	✓ S/U S
c)	Riding Quality	✓ S/U S
d)	Road Camber	✓ S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NO Provisions
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No YES
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U Not provided S
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No YES
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: IHAMBHU KUMAR
THAKUR


03-12-2020
(AE)

Sambhu
03/12/2020
(Signature)(JE)