## FIELD INSPECTION REPORT District: 03.12.2020 Date of Inspection: Length (Km): Klaragfur- Janipus BISLAN PUT- to GOADVAIL 109 Division: Name of the Road: SIM 51 (NEW) MAINTENANCE Scheme/Programme: Road Id No.: Package No.: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/Maintenance Work is a case of: Remarks Parameters to be checked Sl. No. 1 Pavement VS/U Road Junction condition a) VS/U Condition of Surfacing b) √S/U Riding Quality c) JS/U Road Camber d) Whether free from defects such as visible cracks, exposed Yes/No e) aggregates in case of CC Pavement. Ves/No Contraction Joints provided or not (CC Pavement) f) Yes/No Compaction of flank/slope & raincuts if any g) **Cross Drainage** 2 Condition of head walls in Hume pipe culverts including its S/SRI/U a) painting S/SRI/U Condition of Abutment & Wing walls, Slab in RCC culverts MA' b) S/SRI/U Condition of railings/slab/approach for Bridges c) 3 Road Furniture Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and Yes/No a)

Overall Rating:

4

a)

Satisfacory (S)	
Satisfacory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Ram Darskan Ram.
DESIGNATION: J.E.

maintained

**Compliance History** 

Status of ATR's & any others

(Signature)

NO .