	TON DEDORT	
	FIELD INSPECTION REPORT	20.
DATE OF INSPECTION:	03/12/2020 DISTRICT: Pyrneg.	
DIVISION:	DUANDA HA LENGTH: 2'SOKY	
NAME OF THE ROAD:	Thankua Thalari Road (Mushari 70k) to Pakari pa.	
SCHEME/PROGRAMME:	MAINTENANCE (MR-3054 New)	
PACKAGE No:	ROAD ID No.: 220001861	
	ONGOING/COMPLETED/UNDER MAINTENANCE	
STATUS OF THE PROJECT:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
WORK IS A CASE OF:	PARAMETERS TO BE CHECKED	REMARKS
SL.NO		
11	PAVEMENT	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Α	ROAD JUNCTION CONDITION	S
В	CONDITION FO SURFACING	S
C	RIDING QUALITY	S
D	ROAD CAMBER	=======================================
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	Yes
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N·A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	yes
2	CROSS DRAINAGE	
	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS	N. A
Α	PAINTING CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N·A
В	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N. A
c	ROAD FURNITURE	
3	WINDSTALES CICAL BOARDS /INFORMATORY BOARD/ KM & 200 M	Ye2
A	STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	
4	COMPLIANCE HISTORY	NO ANY ATR
Α	STATUS OF ATR"S & ANY OTHERS	, , ,
VERALL RATING		S
	SATISFACTORY(S)	_
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U)	- ,

NAME: Kamal Maryon sharma DESIGNATION: Junier Engineer