FIELD INSPECTION REPORT		
DATE OF INSPECTION:	03/12/2020 DISTRICT: PURNEA	
DIVISION:	DHAMDAHA LENGTH: 2.750/cm.	
NAME OF THE ROAD:	PWD Road More Teldiha - Dhusar	
SCHEME/PROGRAMME:	MAINTENANCE	
PACKAGE No:	ROAD ID No.: 226001866	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	yes s
В	CONDITION FO SURFACING	y - 3
C	RIDING QUALITY	2
D	ROAD CAMBER	S
	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	Yes
E F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	NA
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	yes
2	CROSS DRAINAGE	
	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	NIA
AB	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N·A
c	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N· D
3	ROAD FURNITURE	
Α	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	YRS
4	COMPLIANCE HISTORY	
Α	STATUS OF ATR"s & ANY OTHERS	No Vinh was
OVERALL RATING		,
OVERALL NATING	SATISFACTORY(S)	3
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
	UNSATISFACTORY(U)	<u> </u>

NAME: Kanny Naryan Sharma. DESIGNATION: Junior Engineer

Scanned with CamScanner