FIELD INSPECTION REPORT

3

			CHON REPORT	
Date	of Inspection : O'	3-12-2020	District: (Saran) ch	1/06.4
Division: Chappa-1			I amount ()	4054
	of the Road: N	chammadows.	to Lalbur 3.285	
	ne/Programme:	MAINTENANCE	(NAW M/R)	,
acka	ge No .: PAICA	1 CHALDOIS	Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Un gradation/ Maintenance				
PER PE	4.000,000 2 2 2 2			WMIR)
J. No		Parameters to be checked		Remarks
1.	Pavement			les .
a)	Road Junction condition			S/U
b)	Condition of Surfacing			√S/U
c)	Riding Quality			√S/U
d)	Road Camber			VS/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No-
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	e		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)		Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Furniture	t in the second		Will make the
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
- Intal	Compliance His	itory		MARKET
	Status of ATR's & any others			Charles of the control of

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

03/12/2010

A.B

(Signature)

NAME:

DESIGNATION: