

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: Kaimur	
Division : Mchaniya		Length (km): 13.40 Km	
Name of the Road: Awanhi Rampur Bangla Morath via Sotwa Link Path.			
Scheme/Programme: MAINTENANCE		MR - 2018	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		ongoing.	
Work is a case of: New Connectivity/Up gradation/ Maintenance		up gradation	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

note: - work NOT started

21/12/20
(Signature) (J.E.)

NAME: Santosh kr Puriy