FIELD INSPECTION REPORT

Date of Ins Division : Name of th	pection:		District:	diamps	1
Name of th		3 3 280 7	Length (km):	8.00 KJ	00 m20 Co
	D 1	40 00 100K	District: (4 Length (km): 1 DV2 10 1000 Carve R	Day N. A. D.	777
		MAINTENANCE			
Scheme/Pro	9.		Road Id No.:		
Package No		Ongoing/Complet	ed/Under Maintenance		
Work is a		New Connectivity	/Up gradation/ Maintenance		
Sl. No.		Parameters	to be checked	Remarks	
	Payement			√S/U	
	Road Junction condition			√8/U	
b) (Condition of Surfacing			√S/Ü	
c) 1	Riding Quality				
	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	NA
	Contraction Joints provided or not (CC Pavement)			Yes/No -	>
-5	Compaction of flank/slope & raincuts if any			Yes/No	a loss)
2,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			s/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	TNA
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
M. 2000-0-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	10 8008
4.	Compliance I	History			3
a)	Status of ATR's & any others			No	
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1 14	
Overail R	ating :	Satisfactory (S	3)		i Din
		- Productive to the	ut requires Improvement (SRI)	2	
		Unsatisfactory			4