

# FIELD INSPECTION REPORT

|                                                                                                   |                        |
|---------------------------------------------------------------------------------------------------|------------------------|
| Date of Inspection : 03/12/2020                                                                   | District: Kaimur       |
| Division : Mohaniga                                                                               | Length (km): 2.750 Km. |
| Name of the Road: Ramgrah-chousa Road to Isari                                                    |                        |
| Scheme/Programme: MAINTENANCE                                                                     |                        |
| Package No.:                                                                                      | Road Id No.:           |
| Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance    |                        |
| Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance |                        |

| Sl. No. | Parameters to be checked                                                                                        | Remarks     |
|---------|-----------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | Pavement                                                                                                        |             |
| a)      | Road Junction condition                                                                                         | ✓ S/U       |
| b)      | Condition of Surfacing                                                                                          | ✓ S/U       |
| c)      | Riding Quality                                                                                                  | ✓ S/U       |
| d)      | Road Camber                                                                                                     | ✓ S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No      |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No      |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | ✓ Yes/No    |
| 2.      | Cross Drainage                                                                                                  |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓ S/SRI/U   |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | ✓ S/SRI/U   |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | ✓ S/SRI/U   |
| 3.      | Road Furniture                                                                                                  |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m Yes/No |
| 4.      | Compliance History                                                                                              |             |
| a)      | Status of ATR's & any others                                                                                    | No.         |

NA

ongoing.

Overall Rating :

ongoing work.

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

03/12/2020  
(Signature) J.E

NAME: Santosh Kumar Tiwary