FIELD INSPECTION REPORT

2)12/20	District: Am of obed	
dorsen	Length (km): 5-35/cm	
	Roed to Che N	
MAINTENANCE	Maintena poly 20/8	
	Road Id No.:	
Ongoing/Completed/Under Maintenance		
New Connectivity/Up gradation/ Maintenance		
	Rafigurs MAINTENANCE Ongoing/Completed	

Work is a case of: New Connectivity/Op graduation/ ivialinenance		n de la	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Above Maintin faed new Maintin Polory
Raad hes been pot loss adremany
work in forgres
(Signature)

Konstandw Prosan NAME:

DESIGNATION: UE