

Latitude: 26.08764  
 Longitude: 85.063878  
 Elevation: 59.58m  
 Accuracy: 9.0m  
 Time: 03-12-2020 13:25

### FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	MUZAFFARPUR
Division :	R.W.D. MUZ- WEST	Length (km):	1.05 KM
Name of the Road:	Paroo Sthani Jalg - Paroo Pathi		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/MU/MUZ/19/0027	Road Id No.:	NEA220002628
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	- S -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

*[Signature]*  
 (Signature) 3/12/2020

NAME: K.K. Gupta

DESIGNATION: - A.E