

Block - Goradli h.

FIELD INSPECTION REPORT

Date of Inspection:	3.12.20	District:	Bhagelpr.
Division:	(Goradli) Bhagelpr.	Length (Km):	2.970
Name of the Road:	Mirzanhat to Nadiyama PMSY (Zamin) to Ghelpr.		
Scheme/Programme:	MAINTENANCE		
Package No.:	13 (WombN)	Road Id No.:	NEA 22000439
Status of the Project:	Ongoing/completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
SL. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No	
g)	Cmpaction of flank/slope & raincuts if any	NA Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	NA S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	NA S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	NA S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓	
4	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory(S)	✓
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	✓

(Signature)

Oh
3.12.20
m