

FIELD INSPECTION REPORT

Block - Goradiah.

Date of Inspection: 3.12.20 District: Bhagalpur.		
Division: (Goradiah) Bhagalpur Length (Km): 5.40km.		
Name of the Road: mirjankhat to Nadiyama pmsy (mohambur) to Hazudih.		
Scheme/Programme: MAINTENANCE		
Package No.: Group No - 13 Road Id No.: NEA 22 000441.		
Status of the Project: Ongoing/completed/Under Maintenance		
Work is a case of : New Connectivity/Up gradation/ Maintenance		
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. HA	Yes/No
f)	Contraction Joints provided or not (CC Pavement) NA	Yes/No
g)	Cmpaction of flank/slope & raincuts if any NA	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting NA	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges NA	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory(S)	1
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	1

(Signature)

3.12.20
m

NAME: D. N. Devergi.