

In tender process

Block - Pirpainti

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Bhagalpur	
Division : Kachalgaon		Length (km): 2.73 Km	
Name of the Road: NH-80 to Meharpur via Jaisram Baudhu			
Scheme/Programme: MAINTENANCE		New Maintenance policy	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance In tender process	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NA
4.	Compliance History		
a)	Status of ATR's & any others	No	

- This Road is in tender process

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

Signature
03/12/2020
ME

NAME: