

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Bhagadpur	
Division : Kahaogaon		Length (km): 3.0 KM	
Name of the Road: Gopadpur More to Sabour NH-80.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ☒	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	NA
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	Yes/No	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	S/SRI/U	NA
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture	Yes/No	NO
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	N/O	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NA

(Signature)

A. A.

3.12.2020

AE

NAME: