

# FIELD INSPECTION REPORT

... ..  
(Block - Shahkum)

Date of Inspection: 03/12/2020		District: Bhagalpur
Division: Bhagalpur		Length (Km): 3.370 KM
Name of the Road: Shahkum Aarganj Road (Jageramore) to Sageria		
Scheme/Programme: MAINTENANCE		NEA-22000512
Package No.: / Group No.: - 07		Road Id No.: NEA 22000512
Status of the Project: Ongoing / completed / Under Maintenance		
Work is a case of : New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks
1	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating : Work in Progress.

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

rd  
03/12/20  
(Signature)

NAME: Neeraj Kumar

DESIGNATION: JE