

FIELD INSPECTION REPORT

(Block - Shahkud)

Date of Inspection : 03/12/2020 District : Bhagalpur		
Division : Bhagalpur Length (Km) : 3.87 km		
Name of the Road : Shahkud Amarapur PWD Reth to Amba Badiya.		
Scheme / Programme : MAINTENANCE		
Package No. / Group No. - 8 Road Id No. : NKA22000515		
Status of the Project : ☒ Ongoing / ☐ Completed / ☐ Under Maintenance		
Work is a case of : ☒ New Connectivity / ☐ Up gradation / ☐ Maintenance		
SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating : Work has not been started yet.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	NA

03/12/2020
(Signature)

NAME : Neeraj Kumar

DESIGNATION : J-E