## Agreement done but work not started

## FIELD INSPECTION REPORT

Date of Inspection :	3/12/20	District: Rohfas
Division: Penri		Length (km): 2.500
Name of the Road: B	usar Canal - Bh	Shawa Via Malmari
Scheme/Programme:	MAINTENANCE	
Package No.: 0	MR 2019-20	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	b) Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	
		-

Overall Rating

Satisfactory (S)	9
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Om hakash Kuman

DESIGNATION: J. 6

Scanned with CamScanner