FIELD INSPECTION REPORT

Si da alter		THE THE PART OF TH	TON KEPORT	
120 - 200	f Inspection : 6	3-12-2020	District: Tomas	_
Divisio	n:	Thank	Jane	
Name (of the Road: D	hamha Til 201	Length (km): 2.00	
Scheme	Programme:	MAINTENANCE (tor Harlanja - Cha	P9
Packag	c No.: RMISAIJ		Mell mant, policy	
Status o	of the Project:		Road Id No.: NEA22000	742
Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Sl. No.	the of the	The state of the s		
SI. 140.	And Building	Parameters to be checked Remar		
+1.	Pavement		LHIBSON FOR	4 8 475
a)	Road Junction condition			78.5
b)				S/U
-0)	Condition of Surfacing			S/U
c)	Riding Quality			
d)	Road Camber			S/U
				5/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in D.C.			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
gen allegan	Filteral to a fee			S/SRI/U
3.	Road Furnitur	9		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.			Yes/No

stones/Pavement road markings are provided and maintained

Overall Rating

4:

a)

Satisfactory (S)	'C'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Anister Rahman DESIGNATION: Executive Eigineer

Compliance History

Status of ATR's & any others

Executive Engineer Rural Works Department Works Division, Jhajha

Yes/No