		FIELD INSPI	ECTION REPORT	
Date of Inspection: 31121)20			District: Aurongewad	483
Division: Dandnoger			Length (km): 4.90 KM	51
The second second	Programme:	MAINTENANCE	other have to Jamyama	,
Package		MAINTENANCE	Road Id No.:	100
	f the Project:	Ongoing/Complete	ed/Under Maintenance	124
Work is	a case of:	New Connectivity/	Up gradation/ Maintenance	
Sl. No.		Parameters t	o be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
(h)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	e de la companya de l		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4	Compliance Hi	story T		
的社员	Status of ATR's	continued to be a second		
erall Ra		Unsatisfactory (U		
ae: K	nslande		iern Maintare Poloj Ksign	d gj/h/): ature)
IGNAT	10n: ^{J) [}			