

FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020	District: Kaimur
Division: Bhabua	Length (km): 1.20 km.
Name of the Road: Ratwar-Tigri Road to Rupur	
Scheme/Programme: MAINTENANCE	
Package No.: A/R-N/2019/20/03	Road Id No.: NEA 22000827
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓SU -
b)	Condition of Surfacing	✓SU
c)	Riding Quality	✓SU
d)	Road Camber	✓SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U (
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U-) N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Shashi Bhushan Singh

DESIGNATION: Executive Engineer.

03/12/20
(Signature)