


FIELD INSPECTION REPORT

Date of Inspection : 2.12.20	District: Kewinuv
Division : Phake	Length (km): 3.90 Km
Name of the Road: Kewin chand Durgawati Road (Amraon) Bahyara	
Scheme/Programme:	MAINTENANCE
Package No.: BNR-N/2019-20/02	Road Id No.: NEA 22000968
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓ N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U ✓ N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


2.12.20
(Signature)

NAME: P. P. Singh

DESIGNATION: Assistant Engineer