

FIELD INSPECTION REPORT

Date of Inspection : 2-12-20	District: Kaimosi
Division : Riche	Length (km): 5.420
Name of the Road: Kibari Channel Road Dnyfawati (Chavry) to Duthi	
Scheme/Programme:	MAINTENANCE ✓
Package No.: BR-N/2019-20/14	Road Id No.: NEA 22000994
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U -
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	4th NO.

Overall Rating :

Satisfactory (S)	Sri
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature) 2.12.20

NAME: Bipin Bishari Singh

DESIGNATION: Assistant Engineer