

MR (3054)

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Sitamarhi
Division : SITAMARHI	Length (km): 5.550 KM
Name of the Road: सीटी मोड़ (6th KM NH-77) से ब्रिज नगर पर	
Scheme/Programme: MAINTENANCE	M/R (3054)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under-Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U (S)
b)	Condition of Surfacing	S/U (S)
c)	Riding Quality	S/U (S)
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	✓Yes/No NO
2.	Cross Drainage NA	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S ✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020
(Signature)

NAME: SURENDRA KUMAR SINGH

DESIGNATION: SE