

MR (3054)

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Sitamarhi
Division :	SITAMARHI	Length (km):	2.350 KM
Name of the Road:	NH-77 सोनवडी से जमुना बराही		
Scheme/Programme:	MAINTENANCE (3054)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/H (S)
b)	Condition of Surfacing	S/H (S)
c)	Riding Quality	S/H (S)
d)	Road Camber	S/H (S)
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	NA
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020
(Signature)

NAME: SURENDRA KUMAR SINGH

DESIGNATION: SE