

FIELD INSPECTION REPORT

Date of Inspection :	3-12-20	District:	Bhojpur
Division :	ATA	Length (km):	3.146
Name of the Road:	Banella to chasi Road		
Scheme/Programme:	MAINTENANCE	MR-3054 (New)	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance <i>ongoing</i>		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	<i>Patch work is completed. SDRB is not done till date.</i>
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<i>2m Logo board is established at site</i> Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

3/12/20
(Signature)

NAME:

अशोक कुमार मिश्रा
मुख्य अभियंता-1
ग्रामीण कार्य विभाग
बिहार, पटना

DESIGNATION: