## FIELD INSPECTION REPORT

Date of Inspection :	33-12-2020	District: GOPALGANS	
Division: GOPALO	ANJ-1	Length (km): 1.10 KM	
Name of the Road: NH	128 BANJARI	SE HIRA THAKUR KEGHAR TAK	
Scheme/Programme:	MAINTENANCE	BRAHMA STHANTAK	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/	Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g) -	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	<b>加</b>
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: EY KAMLESH CHAUDHARY

DESIGNATION: CE-3, RWD