

FIELD INSPECTION REPORT

Date of Inspection : 3+2-20	District: Bhojpur
Division : AR9	Length (km): 3.25 km
Name of the Road: Laxadhi PWD Road to Laxadhi gaon.	
Scheme/Programme: MAINTENANCE	MR-3054 (New)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Logo board is not established.
Road marking, signage and Road Furniture is not found at site.

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

(Signature)

NAME:

अशोक कुमार मिश्रा
मुख्य अभियंता-1
ग्रामीण कार्य विभाग
बिहार, पटना

DESIGNATION: