

FIELD INSPECTION REPORT

Date of Inspection : 3-12-20	District: Bhojpur
Division : ARA	Length (km): 5.410 Km
Name of the Road: Baruna - Nandur Agion to Bag bridge tail	
Scheme/Programme: MAINTENANCE	MR-3054 (New)
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	ongoing.
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Partial patch work to be done. only sign board is established
a)	Road Junction condition	S/U at site N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No only sign board established
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

अशोक कुमार मिश्रा

मुख्य अभियंता-1

DESIGNATION:

ग्रामीण कार्य विभाग

बिहार, पटना